Attachment 2:
Machado Lake
Nutrient TMDL
Year 1
Dry Event 1
Monitoring Site
Photos



10_ACAD_1



10_ACAD through manhole



10_EAST-1



10_EAST-2



30_VERSEP Looking downstream



30_VERSEP Looking upstream



31_ASHB_1



31_ASHB_2



31_NORMP looking downstream



31_NORMP looking upstream



20_SCBG looking upstream



20_SCBG looking downstream



20_SCBG Outfall



30_VAND looking downstream



30_VAND looking upstream